GOVWERNMENT OF ANDHRA PRADESH ABSTRACT

Establishment - APGLI Department -Sanction of Additional Budget of Rs. 10.00 lakhs towards repairs to 6th floor roof and repairs to Toilets and Urinals of entire building - Orders - Issued.

FINANCE (ADMN.II) DEPARTMENT

G.O.Rt.No. 428 Dated: 06.02.2010 Read the following:

From the Director of Insurance, A.P., Hyderabad. Lr.No. 14/K2/2007-2008, dated: 17.12.2009.

* * *

ORDER:

In the reference read above, the Director of Insurance has stated that the Insurance Building Complex was constructed in the year, 1984 with 6 (Six) floors, and Mezzanine floor. Director of Insurance and its two Subordinate Offices viz. District Insurance Office, Hyderabad and Ranga Reddy are being accommodated in third and Mezzanine floors respectively. The other floors have been let out to the following mentioned Government Offices.

- 1. Pay and Accounts Office.
- 2. Director of Treasuries and Accounts.
- 3. Commissioner of Small Savings.
- 4. Commissioner of AYUSH.
- 5. Director of State Audit.
- 2. The Director of Insurance has stated that in the Insurance Building Complex the Director of State Audit, tenant Department of 6th and also top floor has requested several times for immediate repairs to the terrace of the building as it is leaking and causing serious problem to the records and machines of his Office. The pipeline and fittings of toilets of the Insurance Building also require urgent repairs. Due to leakage of Pipeline, much inconvenience is being caused to the staff and visitors of Insurance Building Complex, and it may effect the walls of the building and as such the repairs are required urgently. Further, he has informed that due to leakage of the water pipelines, the Generator room is completely damaged.
- 3. The Insurance Department has requested the Executive Engineer (R & B) North Building Complex, Nampally, Hyderabad to inspect the building and suggested his Department to rectify the leakage to the roof of IBC. Accordingly, the Executive Engineer (R & B), North Building Complex, Nampally, Hyderabad inspected the Insurance Building Complex and submitted the estimates for Rs. 10.00 Lakhs vide Lr.No.DB/HD/E.E./R&B/N.B.D./1441, dated:10.11.2009 to under take the repairs of roof along with overhead tanks replacement and repairs to water pipelines.
- 4. Therefore, the Director of Insurance has submitted proposal to accord necessary administrative sanction for Rs. 10.00 lakhs for carrying out repairs to 6th floor roof and repairs to Toilets and Urinals and replacement of overhead tanks and pipelines of entire Insurance Building Complex.

- 5. After careful examination of the proposal of the Director of Insurance, Government hereby accord sanction for Rs. 10.00 Lakhs (Rupees Ten Lakhs only) towards repairs to the 6th floor roof and repairs to Toilets and Urinals of entire building in relaxation of Treasury Control orders.
- 6. The expenditure sanctioned in above para shall be debited to the Head of Account MH 2235-60-405 SH (74) Building 270/272 Maintenance. The Director of Insurance shall send supplementary estimates at appropriate time during the current year.
- 7. The Director of Insurance shall take further action in the matter and to deposit the above amount with P.A.O. (Works and Projects) for the said work through Executive Engineer (R&B), North Building Complex, Nampally, Hyderabad at an early date.
- 8. Copy of this order is available on Internet and can be accessed at address http://www.ap.gov.in.goir.

(BY ORDER AND IN THE NAME OF THE GOVERNOR OF ANDHRA PRADESH)

L.V. SUBRAHMANYAM PRINCIPAL SECRETARY TO GOVERNMENT (FP)

To
The Director of Insurance, AP, Hyderabad.
The Accountant General, AP, Hyderabad.
Copy to
Finance (W&M) Department.
Finance (BG) Department.

//FORWARDED :: BY ORDER//

SECTION OFFICER